
VALIDATION AND CALIBRATION PROCEDURE

Warning: do not validate or calibrate the instrument with standard solutions other than the Hanna Instruments CAL Check™ Standards, otherwise erroneous results will be obtained

For accurate validation and calibration results, please perform tests at room temperature (18 to 25 $^{\circ}$ C: 64.5 to 77.0 $^{\circ}$ F).



Validation **V**

III ZERO

- [] [] -

é•≻


Validation

- 1. Turn the meter on by pressing ON/OFF.
- 2. When the beeper sounds briefly and the LCD displays dashes, the meter is ready.
- 3. Place the CAL Check™ Standard HI96714-11 Cuvette A into the holder and ensure that the notch on the cap is 4-5 positioned securely into the groove.
- 4 Press ZERO/CFM and the lamp, cuvette and detector icons will appear on the display, depending on the measurement phase.
- 5. After a few seconds the display will show "-0.0-". The meter is now zeroed and ready for validation.
- 6 Remove the cuvette
- **7** Place the **CAL Check**™ Standard HI96714-11 Cuvette B into the holder and ensure that the notch on the cap is positioned securely into the groove.
- 8 Press CAL CHECK key and the lamp. cuvette and detector icons together with "CAL CHECK" will appear on the display. depending on the measurement phase.
- 9 At the end of the measurement the display will show the validation standard value. The reading should be within specifications as reported on the CAL Check™ Standard Certificate. If the value is found out of specifications, please check that the cuvettes are free of fingerprints, oil or dirt and repeat validation. If results are still found out of specifications then recalibrate the instrument.

Calibration

Note: It is possible to interrupt the calibration procedure at any time by pressing CAL' CHECK or ON/OFF keys.

- 1 Turn the meter on by pressing ON/OFF
- 2. When the beeper sounds briefly and the LCD displays dashes, the meter is ready.




- 4 Place the CAL Check™ Standard HI96714-11 Cuvette A into the cuvette holder and ensure that the notch on the cap is positioned securely into the groove.
- 5 Press ZERO/CFM and the lamp, cuvette and detector icons will appear on the display. depending on the measurement phase.
- 6 After a few seconds the display will show "-0.0-". The meter is now zeroed and ready for calibration. The blinking "RFAD" asks for reading calibration standard.
- 7 Remove the cuvette.
- 8 Place the CAL Check™ Standard HI96714-11 Cuvette B into the holder and ensure that the notch on the can is positioned securely into the groove.
- 9 Press **READ** ►/TIMER and the lamp cuvette and detector icons will appear on 8 the display, depending on the measurement phase.
- 10 The instrument will show for three seconds the CAL Check™ standard value. Note: If the display shows "STD HIGH". the standard value was too high. If the display shows "STD LOW" the standard value was too low. Verify that both CAL Check™ Standard HI96714-11 Cuvettes. A and B are free of finaerprints 11-13 or dirt and that they are inserted correctly.
- 11 Then the date of last calibration (e.a.: "01.08.2009") appears on the display. or "01.01.2009" if the factory calibration was selected before. In both cases the year number is blinking, ready for date input.
- 12 Press GLP/▲ to edit the desired year (2009-2099). If the key is kept pressed. the year number is automatically increased.
- 13 When the correct year has been set, press ZERO/CFM or READ ►/TIMER to confirm. Now the display will show the month blinkina.
- 14 Press GLP/▲ to edit the desired month (01-12). If the key is kept pressed, the month number is automatically increased.
- 15 When the correct month has been set, press ZERO/CFM or READ /TIMER to confirm. Now the display will show the day blinking.

Calibration **V**


























09.08 2009

16 • Press GLP/▲ to edit the desired day (01-31). If the key is kept pressed, the day number is automatically increased.





- 18 The instrument displays "Stor" for one second and the calibration is saved.
- 19 The instrument will return automatically to measurement mode by displaying dashes on the ICD.













GI P

In GLP mode, the last calibration date can be verified and the factory calibration can be restored.

Last Calibration Date

1 • Press GLP/▲ to enter GLP mode. The calibration month and day will appear on the main display and the year on the secondary display.



2 • If no calibration was performed, the factory calibration message. "F.CAL" will appear on the main display and the instrument returns to measurement mode after three seconds.





0 108

2009

Last Calibration

GLP

Date V

Factory Calibration Restore

It is possible to delete the calibration and restore factory calibration.

- 1 Press GLP/▲ to enter GLP mode.
- 2 Press READ ►/TIMER to enter in the factory calibration restore screen. The instrument asks for confirmation of user calibration delete
- 3 Press ZERO/CFM to restore the factory calibration or press GLP/A again to abort factory calibration restore.
- 4 The instrument briefly indicates "donE" upon restoration of factory calibration prior returning to measurement mode.

Factory Calibration Restore V









BATTERY MANAGEMENT

To save the battery, the instrument shuts down after 10 minutes of non-use in measurement mode and after 1 hour of non-use in calibration mode.

If a valid measurement was displayed before auto-shut off, the value is displayed when the instrument is switched on. The blinking "ZERO" means that a new zero has to be performed.



One fresh battery lasts for around 750 measurements, depending on the

The remaining battery capacity is evaluated at the instrument startup and after each measurement

The instrument displays a battery indicator with three levels as follows:

- 3 lines for 100 % capacity
- 2 lines for 66 % capacity
- 1 line for 33 % capacity
- Battery icon blinking if the capacity is under 10 %.

If the battery is empty and accurate measurements can't be taken any more the instrument shows "dEAd bAtt" and turns off.

To restart the instrument, the battery must be replaced with a fresh one. To replace the instrument's battery, follow the steps:

- Turn the instrument off by pressing **ON/OFF**.
- Turn the instrument upside down and remove the battery cover by turning it counterclockwise.



- Extract the battery from its location and replace it with a fresh one.
- Insert back the battery cover and turn it clockwise to close.

RECOMMENDATIONS FOR USERS

Before using these products, make sure that they are entirely suitable for your specific application and for the environment in which they are used. Operation of these instruments may cause unacceptable interferences to other electronic equipments, this requiring the operator to take all necessary steps to correct interferences.

Any variation introduced by the user to the supplied equipment may degrade the instrument's EMC performance.

To avoid damages or burns, do not put the instrument in microwave oven. For yours and the instrument safety do not use or store the instrument in hazardous environments.





HI96714

Cvanide ISM

Thank You

Thank you for choosing a Hanna Instruments product. Please read this instruction manual carefully before using the instrument.

For more information about Hanna Instruments and our products, visit www.hannainst.com.

For technical support, contact your local Hanna Instruments Office or e-mail us at tech@hannainst.com

Find your local Hanna Instruments Office on www.hannainst.com

PRFI IMINARY FXAMINATION

Please examine this product carefully. Make sure that the instrument is not damaged. If any damage occured during shipment, please contact your local Hanna Instruments Office.

Each H196714 Ion Selective Meter is supplied complete with:

- Sample Cuvettes and Caps (2 pcs.)
- 9V Battery
- Instruction Manual
- Quality Certificate

Note: Save all packing material until you are sure that the instrument works correctly. Any defective item must be returned in its original




For more details about spare parts and accessories see

SPECIFICATIONS


Range	0.000 to 0.200 mg/L
Resolution	0.001 mg/L
Accuracy @20°C (68°F)	±0.005 mg/L $\pm3\%$ of reading
Light source	Tungsten lamp
Light Detector	Silicon Photocell with narrow band interference filter @610 nm
Method	Adaptation of the Standard Methods for the Examination of Water and Wastewater, 18 th edition, Pyridine-Pyrazalone method. The reaction between cyanide and reagents causes a blue tint in the sample.
Environment	0 to 50 °C (32 to 122 °F); max 95% RH non-condensing
Battery Type	9V (1 pc.)
Auto-Shut off	After 10' of non-use in measurement mode; after 1 hour of non-use in calibration mode; with last reading reminder
Dimensions	192 x 104 x 69 mm (7.6 x 4.1 x 2.7")
Weight	320 g (11.3 oz.)

FUNCTIONAL DESCRIPTION



- 1. GLP/A kev: press to enter GLP mode. In calibration mode press to edit the date and time
- 2. CAL CHECK key: press to perform the validation of the meter, or press and hold for three seconds to enter calibration mode.
- 3. ZERO/CFM key: press to zero the meter prior to measurement, to confirm edited values or to confirm factory calibration restore.
- 4. **READ**▶/TIMER key: In measurement mode, press to make a measurement, or press and hold for three seconds to start a preprogrammed countdown prior to measurement. In GLP mode press to view the next screen
- 5. **ON/OFF** key: to turn the meter on and off.
- 6. Liquid Crystal Display (LCD)
- 7. Cuvette alianment indicator
- 8. Cuvette holder

DISPLAY FLEMENTS DESCRIPTION



- 1. The measuring scheme (lamp, cuvette, detector), appears during different phases of zero or reading measurement
- 2. Error messages and warnings
- 3. The battery icon indicates the charge state of the battery
- 4. The hourglass appears when an internal check is in progress
- 5. Status messages
- 6. The chronometer appears when the reaction timer is running
- 7. The month, day and date icons appear when a date is displayed
- 8. Four digit main display
- 9. Measuring units
- 10. Four digit secondary display

MFASUREMENT PROCEDURE

2



































Note: Temperature is a very important parameter for this test method. For best results the sample should have a temperature not exceedina 20 °C.

- 3. Fill a cuvette up to the 10 mL mark with unreacted sample and replace the cap.
- 4. Place the cuvette into the cuvette holder and ensure that the notch on the cap is positioned securely into the groove.
- 5 Press ZERO/CFM and the lamp, cuvette and detector icons will appear on the display. depending on the measurement phase.
- 6 After a few seconds the display will show "-0.0-". The meter is now zeroed and ready for measurement. Remove the cuvette.
- 7 Add 1 level spoon of HI93714A-0 Cvanide Reagent. Remember to close the reagent bottle immediately after use.

Note: Pay attention to the way the spoon is filled: - do not overfill it:

- do not press the powder.
- 8 Replace the cap immediately to prevent the escape of chlorine aas which is developed during the reaction, and shake gently for 30 seconds.
- 9. Wait for 30 seconds and add the content of one packet of HI93714B-0 reagent. Replace the cap and shake gently for 10 seconds
- 10 Immediately add the content of one packet of HI93714C-O reagent, replace the cap and shake vigorously for 20 seconds.
- 11 Replace the cuvette into the holder and ensure that the notch on the cap is positioned securely into the groove. 12 • Press and hold READ ►/TIMER for
- three seconds and the display will show the countdown prior to measurement or alternatively wait for 25 minutes and press READ /TIMER. An audible "beep" indicates the end of countdown period. In all cases the lamp, cuvette and detector icons will appear on the display, depending on the measurement phase.

Note: Shake the cuvette 4 or 5 times viaorously during the first 20 minutes of the timed reading. Accuracy is not affected by undissolved reagent powder.



13 • At the end of measurement, the instrument directly displays concentration in ma/L of cyanide on the LCD. To convert the reading to ma/L of Potassium Cvanide (KCN). multiply by the factor of 2.5.

INTERFERENCES

Interference may be caused by large amounts of turbidity that will cause

Oxidizing (like chlorine) or reducing agents (such as sulfide or sulfur dioxide) are known to interfere with the measurement. Distillation will remove these. Samples with high pH values should be adjusted to approximately pH 7 before testing.

CAUTION: Cvanide, its solution and hydrogen cyanide liberated by acids are very poisonous.

ERRORS AND WARNINGS

On Zero Reading:



Light High: There is too much light to perform a measurement. Please check the preparation of the zero cuvette



Light Low: There is not enough light to perform a measurement. Please check the preparation of the zero cuvette.



No Light: The instrument cannot adjust the light level. Please check that the sample does not contain any debris.

On Sample Reading:



Inverted cuvettes: The sample and the zero cuvette are inverted.



Zero: A zero reading was not taken. Follow the instructions of the measurement procedure for zeroing the meter.



Under range: A blinking "0.000" indicates that the sample absorbs less light than the zero reference. Check the procedure and make sure you use the same cuvette for reference (zero) and measurement



Over Range: A flashing value of the maximum concentration indicates an over range condition. The concentration of the sample is beyond the programmed range: dilute the sample and re-run the test.

During Calibration Procedure:



Standard Low: The standard reading is less than expected.



Standard High: The standard reading is higher than expected.

Other Errors and Warnings:



Cap error: Appears when external light enters in the analysis cell. Assure that the cuvette cap is present.



lamp to cool down.

Cooling lamp: The instrument waits for the

Battery low: The battery must be replaced soon.



dEAd

6AEE

Dead battery: This indicates that the battery is dead and must be replaced. Once this indication is displayed, normal operation of the instrument will be interrupted. Change the battery and restart the meter.

ACCESSORIES

Reagent Sets	
HI93714-01	Reagents for 100 tests
HI93714-03	Reagents for 300 tests
Other Accessories	
HI96714-11	CAL Check™ Standard Cuvettes (1 set)
HI740029P	9V battery (10 pcs.)
HI731318	Cloth for wiping cuvettes (4 pcs.)
HI731331	Glass cuvettes (4 pcs.)
HI731335	Caps for cuvettes (4 pcs.)
HI93703-50	Cuvette cleaning solution (230 mL)

WARRANTY

HI96714 is warranted for two years against defects in workmanship and materials when used for its intended purpose and maintained according to the instructions.

This warranty is limited to repair or replacement free of charge. Damages due to accident, misuse, tampering or lack of prescribed main-

tenance are not covered If service is required, contact your local Hanna Instruments Office. If under

warranty, report the model number, date of purchase, serial number and the nature of the failure. If the repair is not covered by the warranty, you will be notified of the charges incurred.

If the instrument is to be returned to Hanna Instruments, first obtain a Returned Goods Authorization Number from the Customer Service Department and then send it with shipment costs prepaid. When shipping any instrument, make sure it is properly packaged for complete protection.

To validate your warranty, fill out and return the enclosed warranty card within 14 days from the date of purchase.

Hanna Instruments reserves the right to modify the design, construction, or appearance of its products without advance notice.

All rights are reserved. Reproduction in whole or in part is prohibited without the written consent of the copyright owner, Hanna Instruments Inc., Woonsocket, Rhode Island, 02895, USA

IST96714 01/18