XINTEST Temperature and Humidity Data Logger

Temperature measurement range:-40°C to 125°C （external sensor）

Temperature measurement accuracy: ±0.3°C @ 25°C

Temperature display resolution: 0.1°C

Humidity measurement range: 0 to 100%RH

Humidity measurement accuracy: ±2% RH @ 25°C

Humidity display resolution: 0.1% RH

Operate/Storage temperature:-40 to 105°C (external sensor)

Selectable measure Interval:1 second to 24 hours

Record 21,000 temperature and humidity counts simultaneously

LCD display indication

Battery: 3V,AAA x 2

External sensor

-Humidity Range:0 to 100%RH

-Log memory:21,000 T/H counts simultaneously -Dual Control: Manual Setting or through PC

-LCD Display: Temperature, Humidity,

 Threshold Alert, Settings,Clock

-Data analysis: PC download for archive and

 analyses, Dew Point indication

-Battery:(non-lithium)AAA battery,