Calipers

An industry standard in measuring tools

ABSOLUTE Digimatic Caliper 500 Series — with exclusive ABSOLUTE Encoder Technology

- Electromagnetic induction system allows use in workshop conditions exposed to coolant, water, dust oil.
- New ergonomic design with finger rest.
- The ZERO/ABS button allows the display to be Zero-Set at any slider position along the scale for comparison measurements. This button will also allow return to the absolute (ABS) mode and display of the true position



from the origin (usually jaws closed point).

- Large and clear LCD readout.
- Smooth slider movement makes for comfortable operation.
- 18,000 hours battery life.
- Allows step measurement.
- Carbide-tipped jaw calipers are optimal for rough finished parts, castings, grinding stones, etc.
- Allows integration into statistical process control and measurement systems for models with measurement data output connector. Refer to page A-3.





Technical Data

Accuracy: ±0.02mm (≤200mm), ±0.03mm (≤300mm)

(excluding quantizing error)

Resolution: 0.01mm or .0005 "/0.01mm

Repeatability: 0.01mm Display: LCD

Scale type*: ABSOLUTE electromagnetic induction linear

encoder

Max. response speed: Unlimited Battery: SR44 (1 pc), 938882,

for initial operational checks (standard accessory)
Battery life: Approx. 3.5 years under normal use (18,000

hours for continuous use)



A built-in ABS (absolute) scale means that these calipers are ready to use immediately after power-on without origin resetting – just like using a vernier caliper.




Optional accessories

Dedicated for the models equipped with a digimatic output function. For details, refer to page A-21.

959143: Data hold unit





Connecting cables for IT/DP/MUX

959149: SPC cable with data button (1m) 959150: SPC cable with data button (2m)



USB Input Tool Direct

06ADV380C: SPC cable for USB-ITN-C (2m)

Connecting cables for U-WAVE-T

02AZD790C: SPC cable for U-WAVE with data button (160mm)

02AZE140C: SPC cable for footswitch

Functions

Absolute measurement: After power is turned ON, measurement can be started without zero-setting if origin-setting was previously performed. The Absolute origin position can be changed by the ORIGIN button.

Incremental measurement: Display can be set to zero at any arbitrary position for comparative measurements

Low-voltage alert: If the battery voltage becomes low, a "B" appears in the display to alert the user before measurement is no longer possible. A battery change advisory alert precedes this alert.

Data output: By using the connecting cable (option), measurement data can be output.

Data hold: By using the data hold unit (option), the displayed value can be held. This cannot be used with the data output function.

SPECIFICATIONS

Metric	ı			
Order No.	Range	Depth bar	Fine adjustment	Remarks
500-150-30	0 - 100mm	ø1.9mm rod	with thumb roller	
500-180-30*			_	_
500-151-30	0 - 150mm	Blade	with thumb roller	
500-154-30				Carbide-tipped jaws for outside measurement
500-155-30				Carbide-tipped jaws for outside and inside measurement
500-158-30		ø1.9mm rod		
500-181-30*			_	_
500-152-30	0 - 200mm 0 - 300mm	Blade	with thumb roller	
500-156-30				Carbide-tipped jaws for outside measurement
500-157-30				Carbide-tipped jaws for outside and inside measurement
500-182-30*			_	
500-153			with thumb roller	_

^{*} without SPC data output

Inch/Metric						
Order No.	Range	Depth bar	Fine adjustment	Remarks		
500-170-30	0 - 4"	.075" rod	with thumb roller			
500-195-30*				_		
500-171-30	0 - 6"	Blade				
500-174-30				Carbide-tipped jaws for outside measurement		
500-175-30				Carbide-tipped jaws for outside and inside measurement		
500-178-30		.075" rod		_		
500-196-30*		Blade				
500-159-30*				Carbide-tipped jaws for outside measurement		
500-160-30*				Carbide-tipped jaws for outside and inside measurement		
500-172-30	0 - 8"			_		
500-176-30				Carbide-tipped jaws for outside measurement		
500-177-30				Carbide-tipped jaws for outside and inside measurement		
500-197-30*				_		
500-163-30*				Carbide-tipped jaws for outside measurement		
500-164-30*				Carbide-tipped jaws for outside and inside measurement		
500-173	0 - 12"			_		
500-167				Carbide-tipped jaws for outside measurement		
500-168				Carbide-tipped jaws for outside and inside measurement		
500-193*			_			
500-165*				Carbide-tipped jaws for outside measurement		
500-166*				Carbide-tipped jaws for outside and inside measurement		

^{*} without SPC data output

DIMENSIONS

