

## GM1361 Temperature & Humidity Meter



[Click here to view product](#)

<b>Product Code</b>	XE-4012-001
<b>Model</b>	GM1361 Temperature & Humidity Meter
<b>General Description</b>	Supplied in hard carry case
<b>Type</b>	K-type thermocouple temperature measuring
<b>Accuracy of temperature</b>	±1°C or ±1.8°C
<b>Accuracy of humidity</b>	± 3%(30-95%); ± 5%(10-30%)
<b>Battery</b>	9V Battery
<b>Dimensions</b>	160*70*30mm
<b>Function #1</b>	Large LCD temperature & humidity dual display
<b>Function #2</b>	Data hold

<b>Function #3</b>	Low battery indication
<b>Function #4</b>	Auto /Manual power shut off
<b>Function #5</b>	Max/ Min function
<b>Input Range - Type K</b>	-10°C ~ 50°C (-30°C ~ 1000 °C K-type)
<b>Humidity range</b>	5%RH ~ 98%RH
<b>Unit selectable</b>	°C / °F selection
<b>Sampling rate</b>	2.5times/sec