

XINTEST HT-86 Mini temperature and humidity meter



Specifications	
Humidity range	0~100%RH
Temperature Range	-30°C~100°C(-22°F~199°F)
Dew point Temperature	-30°C~100°C(-22°F~199°F)
Wet Bulb temperature	(0~80°C/32-176°F)
Humidity accuracy	±2%RH(at 25°C,20%~80%RH) ±2.5%RH(at other ranges)
Air temperature Accuracy	±0.5°C/0.9°F(at 25°C) ±0.8°C/±1.5°F(all other ranges)
Resolution	0.01%RH,0.01°C/0.01°F.
Response Time	%RH:10s(90%at +25°C still air)
Battery Type	9v Battery NEDA 1604,IEC 6F22
Operating Temperature	32°F to 104°F(0 °cto 40°C); <80%RH
Storage Temperature	32°F to 104°F(0 °cto 40°C); <80%RH

Size(HxWxD): 175mm*58mm*35mm

Weight:143 g

Accessories: 9V battery, user manual ,blister card

