

## XINTEST HT-521 O2 Oxygen meters

### Features

- Digital LCD display
- auto zero
- high accuracy, quick response
- pocket size and easy to use
- fast sampling
- max hold
- data hold
- auto power off



### Specifications

Operating temperature	0 to 50°C
Storage temperature	0 to 20°C
Operating humidity	0~90% relative humidity
Measurement range	0 to 30% VOL
Measurement resolution	1ppm
Accuracy	3% or +2VOL
Warm up period	Less than 2seconds
Battery	8v, 4*1.5AAA battery
Auto power off	After 15 minutes of inactivity
Sensor type	Stabilized electrochemical gas-specific
Typical sensor life	3 years
Size	160*55*40mm
Weight	156g
Accessories	1.5AAA*4 battery, manual and blister card

